






# Metalspinning T-Rest Plan



Select proper diameter  
for your lathes's toolpost



Bottom View T-Rest