



Combination Tool



Side View



End View

Use all dimensions (except length) as a general guide. Importance should be placed on smooth radiused edges along with a blemish free, mirror-like surface.

© Ted Sokolowski 2011
www.sokolowskistudios.com